





Flood Inundation in Part of Barak Valley, Assam State

Pre-Flood Resourcesat-2 AWiFS Image of Mar 02, 2022



During Flood IRS SAR Image of May 19, 2022 (0600 Hrs IST)



RRES
National Remote Sensing Centre, ISRO
Dept. of Space, Govt. of India
Hyderabad- 500 037
E-Mail: flood@nrsc.gov.in
www.nrsc.gov.in

Location Map

