



ASSAM FLOODS - 2019

- Heavy incessant rains followed by rise in the water levels of Brahmaputra and its tributaries has led to severe flood situation in more than 29 districts of State
- All the major tributaries of River Brahmaputra were flowing above danger level due to heavy rains during the Second week of July, 2019.
- NRSC acquired Sentinel-1A SAR data of Jul 10th and RADARSAT-2 SAR satellite data of 12th & 14th July 2019 to map & monitor the flood inundated areas.
- The flood inundation information was disseminated to the concerned Central and State Govt. departments and Govt. of Assam.
- The following satellite images show pre & during flood situation in parts of Assam
- For flood map, please visit disaster support services at <https://bhuvan.nrsc.gov.in/>


Resourcesat-2 AWiFS data of 07-Feb-2019



SENTINEL-1A SAR data of 10-Jul-2019



RADARSAT-2 SAR data of 12-Jul-2019 (1800 Hrs)



RADARSAT-2 SAR data of 14-Jul-2019 (0600 Hrs)

